


Example of Tree Protection Signs



Example of Tree Protection Fencing



ING CENTRE
ARK

WILTON SHOPPING CENTRE ACCESS ROAD

WILTON ACCESS ROAD TO
ST. JOSEPH'S SWA WILTON

LEGEND

- Category A (Tree stem and canopy spread)
- Category B
- Category C
- Category U
- Root Protection Area
- Trees & Groups to be removed (to be confirmed)
- Site Boundary
- Existing Layout
- Proposed Layout
- Existing Ground Levels
- Proposed Ground Levels
- Tree Protection Fencing (area within forms Construction Exclusion Zone and is required to protect retained soil, roots, stems and canopies)
- 'No-Dig' Permanent Ground Protection (recommended locations to protect Root Protection Areas)

NOTES

Purpose of Tree Survey
The tree survey has been carried out in accordance with BS5837:2012 Trees in relation to design, demolition and Construction - Recommendations. The purpose is to illustrate the constraints and opportunities posed by trees and hedgerows, to help the design team prepare a layout that is considerate of the existing canopy cover and within influencing distance of the site.

Caution
Tree and hedgerow positions place reliance on topographical survey. The position of trees and hedgerows not recorded on the topographical survey remains indicative.

Scale is for planning purposes only.
Plan should be read in colour and in conjunction with accompanying Tree Schedule.

BS5837 Retention Categories
The purpose of the tree categorization method is to identify the quality and value (in a non-fiscal sense) of the existing tree stock, allowing informed decisions to be made concerning which trees should be removed or retained in the event of development occurring.

Category A
Trees of high arboricultural quality and value in such condition to make a significant contribution for a minimum of 20 years.

Category B
Trees of moderate arboricultural quality and value in such condition to make a substantial contribution for a minimum of 10 years.

Category C
Trees of low arboricultural quality and value currently in adequate condition and able to remain until new planting is established with a minimum useful life expectancy of 10 years, or trees with a stem diameter of <100mm.

Category U
Trees in poor physiological or structural condition that cannot realistically be retained in the context of current land use for longer than 10 years.

Date	Details of Change	By	Version
08.08.24	Insert layout	JM	v1
01.02.25	Insert final layout	JM	v2

Tree Impact & Protection Plan

PROJECT SITE
Wilton ESB, Cork

CLIENT
Land Development Agency

DRAWING REF.
23-417-03

REVISION
Version 2

DATE
01.02.2025

SCALE
1:500@A1

DRAWN BY
JM

CHECKED BY
JL

John Morris Arboricultural Consultancy Ltd
Cork City Centre, Cork City, Ireland. Tel: 021 493 7100. Email: info@johnmorriscork.com. Web: www.johnmorriscork.com

